May 2006 Volume 6, Issue 10

ANODE

Inside this issue:

Editor's Comments

New Ouad at 1 Club House

Noise Surgery 3 101

Editor's Comments

May 2006 Volume 6 Issue 10

Winter Coming on...

What projects should you do during the winter months?

Seen in the Newsgroups...

Can anyone help me with research for my degree.

I'm looking for information on ham radio en-

thusiasts who suffer from depression manic (bipolar syndrome). I ticular form of mental illcally risk. a t

tact with anyone who could help me?

Thanks Gerry G.

XP SP2 "breaks" some DOS programs.

have a theory about rf Yes, XP service pack two fields and their effect on does interfere with proelectrical activity in the grams that used to work brain. I believe this par- quite well under Windows XP. Most of the ness could be specifi- DOS amateur radio programs that worked well under MS-DOS worked Can you put me in con-quite well under later versions of Windows. With the drive to more secure computing or the eradication of 'outside interference', this service pack/patch limits (continued on page 2)

New Quad at Club house

Special points of interest:

- Contact details on back page (updated)
- New email address for Anode and ZS6WR. See back page



Editors Comments & News

(continued from page 1)

the access o f 'unmanaged' programs. This is one of the major reasons why Any concerns or comments re-MS wanted to install the .NET framework into the new operat- WILRO 100, please notify us, ing systems.

The "cure" for this problem is simple; use a 'DosBox'. This is a Please convey our greatest apthat functions under both Win- assisted with the event. dows 32 bit systems and Linux. It provides all the low level ac- The Organising Committee cess and support for sound cards.

games, this Open-Source utility able on has 'fixed' a lot of popular ama- www.championchip.co.za. teur radio DOS programs.

You can get it from Source-Forge as an installable program or as a set of source files. Its now at version 0.65. Go to: http://dosbox.sourceforge. net/

WILRO 100 & West Rand **Amateur Radio League**

The Organizing Committee of the WILRO 100 would like to thank you and your team for the invaluable support afforded our race on 30th April 2006.

With the assistance of your members, the support shown to the cyclists was fantastic, and the feedback we received was extremely positive, and overwhelming. It is greatly appreciated, and we hope that we can continue to build a strong and

lasting relationship way into more the future.

> garding this 8th edition of the and we will strive to build on the race forwards.

complete DOS environment preciation to the members that

WILRO 100 Cycle Challenge.

Originally designed to run DOS Results for the race are avail-

Just for Keith! You can now buy these pole-hugging statues for your car aerial.



How to cure the transmitter in your PC.

Does your PC interfere with your two-meter receiver or 137-MHz weather satellite receiver? Do you hear hash, buzzes. or full quieting carriers when your PC does the RAM check, accesses the hard drive or is just sitting idle at the DOS prompt? Read on and I'll tell you how eliminated the noise from my PC. The modifications to your PC will take about four hours and a few inexpensive parts.

History

I use JVFAX on a PC to digitize weather satellite imagery from the NOAA satellites transmitting on 137.5 and 137.62 MHz. You don't need a really fast machine for this software-I used a 286 20 MHz for months. One day I turned on the PC and it wouldn't start. It had died, so I replaced its motherboard with an old 386 25 MHz that I had taken out of our family PC when upgraded it to a 486. With the new motherboard installed. I figured that everything would work as before.

The first time I turned it on and waited for a satellite pass, I thought there was some problem with the receiver or antenna. The signal from the satellite was buried in noise! I quickly shut off the PC and the signal was suddenly in the clear. Uh-oh! Now what do we

do?

I considered changing to a different antenna-one that had the most pickup straight up and not too much off the sides or underneath it. But I knew that wouldn't work, since I wanted get horizon-to-horizon coverage as the satellite moved across the sky. I used my HT to try to locate where the case might be leaking, and found full quieting carriers all over the basement (where my ham shack is located), all over the first floor, and all over most of the second floor of our house. What we had here was a transmitter that covered at least 137 to 148 MHz! My antenna is inside and above the garage, approximately 25 feet above and to the side of the noisy PC. See Fig. 1.

What didn't work?

I knew I couldn't use the rubber ducky to localize the leakage from the PC. The signals were so strong you couldn't tell when you had found a leak in the case by the signal getting stronger. The signals were already full quieting! At this point, I tried putting a clamp-on ferrite filter (see Photo A) on the coax, thinking that interference was being picked up by it and reradiated at the antenna. No difference. I tried a clamp-on filter on the IDE cable at the controller card. No difference. I pulled all the exterior cables from the PC (except for the 115 VAC power cable). No difference. I pulled out all the plug-in cards (video, I/O, disk controller,




Fig. 1. 137 MHZ interference being radiated from the basement PC to the antenna in the garage attic.

interface to weather satellite receiver). No difference. I tried one of the new low emission cases with overlapping/ interlocking (Continued page 4)

(Continued from page 3) mating edges (see Fig. 2). Nope, no difference. Dismally, I envisioned encasing the entire PC in a metal screen.

What did work

Where I work we used to do EMI testing. I remembered seeing a probe (Photo B) that the EMI engineers had used to locate specific components that might be emitting a lot of EMI, or a bad connector that was leaking RF, etc. At the end is a Fig. 2. Low-emission cases utilize of plastic and so doesn't block connector that connected to receiver. I scrounged up three picked a probe at random.

the CPU chip generated a lot of drive, so this noisy. The disk controller card snap-on panel.) was noisy when I accessed the hard drive. As I pulled the Again, where I work, we probe a few inches away from measure the noisy locations, the signals resistance dropped away to nothing. Aha! parts of the So this is how the professionals manufacture. do it!

TOP OF CASE OVERLAPPING AND INTERLOCKING MATING EDGES **BOTTOM OF CASE**

is interlocking panels to create an any RF. Likewise for the big monitor RF-tight enclosure.

coated with a different colour of up the PC and began probing were not rubber to indicate a different all around the case. The worst anything! You don't need a frequency range. All the locations for EMI emission were probe like the one I used to frequency range labelling had the power supply fan air outlet, clean up your PC-just follow my been rubbed off, so I just all along the sides of the case instructions and you should be where the top and bottom able to do it quite easily. panels meet, the I/O expansion I connected it to my "other slots at the back of the PC, and The following parts and tools satellite receiver and began the front of the PC where there will be needed to complete the probing around inside the PC used to be a large five-and-a - job: after powering it up with the quarter-inch hard drive. (I've case open. As I had suspected, since upgraded to an IDE hard 🖫 wrist strap for preventing spot is noise at 137 MHz. The power empty-there is just a big hole supply leads were also very there now, covered by a plastic

> the products we We specify that the bonding resistance be less milliohms-that's .002 ohms. I measured the resistance between the top and bottom

panels at several ohms. This resistance changed value as I lifted the lid on my flip-top case, indicating that the bond between the top and bottom was very poor.

Between the drive bay (the bracket that holds the floppy drives) and the bottom panel, I measured an open circuit. The I/O expansion bracket that holds the plug-in cards was totally isolated from the bottom panel. The fan outlet is a big hole to RF since the fan is made hole that used to hold the hard drive. What I had was a bunch of the old probes. Each was I closed up the case, powered of floating metal panels that connected

- static damage to sensitive motherboard and plug-in cards
- □ screwdriver or small nut driver socket to fit the metal tapping screws
- electrical 🖫 electric hand drill
- between various I rotary wire brush for the hand drill
 - typically set of small-diameter drill bits
 - than 2 🖫 ohm meter that can resolve resistances down to 0. I ohm (most DMMs should work (continued on page 5)

(Continued from page 4) fine)

- sheet approximately
- metal shears to cut the sheet aluminium
- 0.01 pF 1,000 v
- ☐ I miniature DPDT toggle switch rated at 250 VAC, two amps or better
- assortment οf metal self-tapping screws
- □ I ferrite/iron toroid core. about one inch inside diameter
- □ I five-inch- square piece of metal window screen
- \square 10-15 sets of 6-32 x 1/4-inch screws, 6-32 nuts, and size 6 external or internal star washers.

What you are going to do is create an RF-tight case. The static strap so you don't zap any case-must be as near one solid of the parts when you slide piece of metal as possible. All around in your chair and build parts must have good electrical up a nice healthy charge. Its contact with each other. When function is simple: It drains all two panels contact each other the charge from your body to for a long distance, you will the PC chassis through the wire need to provide several points and resistor instead of through of metal-to-metal contact. All the ICs. (This is also a good tool large holes must be covered to have whenever you replace with metal plates or metal boards, add RAM or other screen.

First things first

ribbon the

cables with a small dot of paint or marking pen, then make a aluminium similar dot on your map. See one - Fig. 3. Now go back and sixteenth-inch thick (a few re-check the diagram against the PC itself.

Next, pull the AC cord from the ■ 2 ceramic disc capacitors, PC and the wall. Then get a

for the around connection.) You will need to completely disassemble your PC down to the major component level. Remove the disk drives, power supply, plug-in cards, and motherboard.




Fig. 3. Draw a diagram of your PC's hookup before disassembly.

times when you have your hands inside the PC.) Before touching anything inside, put the band around your wrist. Then connect the alligator clip Begin by making a map to the power supply case. showing where all the cables (Since I had a floating case, I and connectors go. Note which had to pick some point as cable ground. The power supply had connectors go on-most will fit to be connected to all the either way. Mark each of the electronic parts, so I chose it

Fig. 3. Draw a diagram of your PC's hook-up before disassembly.

When removing the power connectors from motherboard and disk drives, be very careful not to apply too much twisting force-you could damage the circuit boards. The power connector on the power supply cable must be tilted away from its mate on the motherboard and then pulled straight up. Practice on a junk board if you've never done it before, get some help from someone who has. Likewise, in reassembling the PC, use minimal force when plugging


(Continued on page 6)

(Continued from page 5) motherboard and disk drives.

apart, including all panels and place. brackets that attach to each bottom of the case.

Power supply

at this point, but I'm not sure the power supply chassis. that this size hole would allow this switch.) Measure the of dust. The resistance between the new power supply aluminium plate added here will run cooler KEYBOARD LOCK and the power supply chassis, i f making sure you have a good components connection.



switch was removed, and the label back and put a few drops

hole sealed -with an aluminium of light oil on the shaft. Some in the power connectors to the plate. The 1201240 VAC switch fans I've seen also have a was removed and its wiring was rubber plug that must be bypassed, and the new on/off removed to get access to the Next take the case completely toggle switch was mounted in its shaft. Seal it back up with the

other with screws. My case is a Remove the voltage selector flip-top that uses screws to hold switch (see Photo C) and solder My drive bay uses plastic drive bay and I/O together the wires that the runners to hold the two floppy expansion bracket (located at selector switch used to short drives. I noticed a grounded the back of the PC) to the together. In its place, mount a spade lug at the connector end miniature DPDT toggle switch; it of the five and a quarter-inch will be the new power on/off drive chassis, so I pushed on a switch. The new switch plugs mating connector (commonly the hole nicely. I doubt that any used in automotive electrical RF would leak out here, but circuits) with a short wire Next we'll modify the power plugging it can't hurt. At the 115 connected to the power supply supply. Mine had a large red VAC input connector, bypass chassis. The three and a plastic bat-handle on/off switch both lines to ground with half-inch chassis didn't have a on the side (see Photo C). I the .01-pF capacitors, using ground lug, so I added one and removed it and covered the short leads. Make sure the connected it to the power suphole with a piece of aluminium. capacitors' leads have a good, ply chassis. The hard drive (I measured a * lot of leakage low-resistance connection to mounted on the side of the

could have just been leaking supply apart, vacuum it out. provided a good ground for the out of the gap between the top Most will have some dust hard drive. and bottom panels right next to inside, and some will have a lot


> t h e don't have a blanket of dust to insulate them.

Remove fan; noting which way it is

you want the air to exit the back view). of the PC. If there is a stick-on Photo C. The large plastic on/off label near the centre, peel the

label or some black electrical tape to keep the dust out.

drive bay using a small bracket made specifically for three and 137 MHz energy to escape. It While you have the power a half-inch drives. This bracket



mounted. When you replace it, Fig. 4. Case Modifications (front

(continued on page 7)

(Continued from page 6)

Drive bay bracket


Case top

Replace the fan, but put a piece Next is the drive bay bracket. Next comes the case top. of metal window screen This bracket is used to hold the Before I removed any paint or between the fan and the power five and a quarter- and three drilled holes I looked along the supply chassis. You will need to and a half-inch floppy drives. edges of the top and bottom punch four holes in the screen An empty space not accessible panels to see where I could put for the screws that hold the fan from the outside would nor- short metal self-tapping screws in place. Use the wire brush mally hold the hard drive but I without damaging and electric drill to remove any have a three and a half-inch inside. I found that I could put chrome-looking coating where hard drive so this large slot was two screws through the top the screws attach the two parts empty. The drive bay bracket in surface at the front and back to of the power supply chassis my PC was attached to the secure the top to the front and together. You want a good, bottom of the case with metal rear panels. See Figs. 4 and 5. low-resistance connection at all tapping screws. screw locations.

paint, so I had to scrub hard to washer between the parts. remove it.

I measured the resistance panels overlapped. Since my Put the power supply back between the drive bay bracket case is a flip-top there are two together. Use the wire brush to and the case and found no large holes at the back where clean up around the holes on connection-another instance of the top pivots. I used the wire the power supply where it a floating part in the PC! I used wheel to remove the paint at attaches to the case rear panel. the wire wheel to remove the these pivot points and put a up the matching paint where the metal screws screw and nut at each hole to locations on the rear panel. My touched the drive bay and put provide a good connection. case had a very thick layer of them back in place with a star

I also put three screws on each side where the top and bottom



Tightening up the screws pro- Fig. 5. Case modifications duced the zero-ohm resistance (rear-view). Note new on/off that is required.

switch in lower-left.

(continued on page 8)

(Continued from page 7) I/O expansion bracket

Next comes the I/O expansion bracket on the back panel. time I switched Front panel motherboards, I had trouble then stop there.

and still the plug-in cards wires barely reach Obviously, these were slotted bracket height.

should have with a blank bracket.

getting cards far enough into Last comes the front panel and make good notes and the motherboard connectors indicator LEDs, push-buttons, diagrams such that the top of the bracket and keyboard lock switch. On everything goes before you would touch the top of the back my chassis, these parts are remove anything. panel. I would tighten the mounted on a plastic bracket screw enough so the bracket that sticks out about an inch would just start to bend and from the front metal panel. I Problems passed all the twisted pairs through a one-inch toroid core I know you don't want to take I checked to see that the just inside the case front panel, apart your PC. After all, it does motherboard was properly Pass the wires through the core work properly and you might placed and was as close to the as many times as possible until screw up something. Also, it bottom of the case as it should you run out of room on the core does look nice. But remember, be. It was as low as it could go or nearly run out of wire and the you can't hear those weather wouldn't go low enough. When location on the motherboard. clearly! I removed the bracket from the The core and wires form an RF while making the changes and rear of the PC, I noticed that choke that stops any RF these clean up that noise! there were slotted holes where wires might pick up from inside it attached to the rear panel. the case and reradiate outside.

to allow adjustment of the When drilling holes in the case the PC won't look as nice as top and bottom, make the hole before since there will be some in the outside panel larger than paint missing where the screws I used the wire wheel to the screw threads so it has some bind the top to the front and remove the paint where the room to move around. The hole rear panels and the top and screws go through and where in the inside panel has to be bottom panels together. Buy the card brackets touch the smaller than the screw thread, some matching touch-up paint expansion bracket. I then put Practice on a piece of scrap and go over the spots ~ Where the motherboard in place, and metal when selecting a drill bit you removed the paint. put the rear panel in place with for the inside panel hole. If the its screws just hand-tight. Then hole is too large, the threads in Another problem is that it will I put a few plug-in cards in the panel will strip away easily, take more work to replace place and adjusted the expan- If the hole is too small, you may cards, since you have to sion bracket so that it just end up breaking off the head of remove so many screws to get touched the underside of the the screw, since the screw is to the inside. Also, the threads card brackets. I tightened the trying to displace so much in the panels will eventually screws that held the rear material. (I've actually broken strip after the screws have bracket to the rear panel and off the head of a screw when been removed/rep laced a few all was as it should be. Problem putting a self-tapping screw times. This can be minimized solved! Any unused slots into steel!) The front and rear

their panels of my PC are steel, so I corresponding hole covered had to select the drill bit sizes properly.

> That's all you should have to do to make your case RF-tight. Remember to take your time, showing

their satellite or packet Proceed

> There are several problems with these modifications. First,

(continued on page 9)

(Continued from page 8) rather than starting a new one the process. each time you put the screw back in place. My advice is to By the way, you might keep this

together.

pictures NOT shown here).

I didn't bother saving any actually (no picture data) every 10 to 20 slowly when making whenever I removed the top of the case matters to you. and began digitizing a satellite interfere! Maybe you won't photos. have to drill any holes in your case top/bottom to silence it. Try all the changes except for drilling holes in the case to see Jim Kocsis WA9PYH if that is adequate for your PC.

Other people have PCs similar and don't have *From* interference. Maybe I had a 73 Amateur Radio Today. very noisy motherboard, an April 1998 exceptionally leaky PC case, a

bad antenna location, or the by starting the screw by hand combination of all these. The to make sure it engages with bottom fine is that I eliminated the thread already in place the noise and I learned a lot in

plan your changes carefully article handy. In the future, PC and make several changes at microprocessor speeds are once if possible, or if you're only going to go up and the unsure of a change, test it be-holes in your case that don't fore you put the case back leak EMI now will let the higher frequencies right through! Microprocessors are running at I've included weather satellite 233 MHz in the new PCs now, pictures showing the quality of with speeds twice that high after the probably not more than a few modifications (Photos D, E, F - years away. The techniques in this article may help you later if you have problems with EMI.

pictures with the noise in them, If you make these changes to so I can't show you how bad your noisy PC I would be were. The interested in hearing from you. pictures before modifications I'd like to know how it helped or had two or three lines of noise if it didn't. Good luck-and go the modifications. Remember, too, program wrote data to the hard that tampering with your PC drive. I wanted to show how might void its warranty if there bad the pictures used to be, so is one-be sure to check this if it

pass. To my surprise there was And finally, many thanks to my no interference in the receiver! wife for helping review this Now I couldn't force the PC to article and to Ben Jagla for the

> 53180 Flicker South Bend IN 46637

The West Rand Amateur Radio Club

26.14122 South - 27.91870 East

P.O. Box 562 Roodepoort 1725

Phone: +27 11 475 0566

Chairman/Treasurer

Email: zs6wrmail@mweb.co.za

[NEW EMAIL ADDRESS]

Dave

Bulletins (Sundays at ...) 11h15 Start call in of stations 11h30 Main bulletin start

Frequencies

439.000MHz 7.6MHz split (West Rand Repeater)

145,625 MHz (West Rand Repeater)

10,135 MHz (HF Relay)

Radio Amateurs do it with more frequency!

	24.0		110 0000 (11)	210400@102.00.124
Vice Chairman	Keith	ZS6AGF	675 1604 (H)	mwbronie@iafrica.com
Secretary	John	ZS6FJ	672 4359 (A/H)	
Digital Communications	Stuart	ZS6OUN	082 573 3359	sbaynes@iafrica.com
Technical	Phillip	ZS6PVT	083 267 3835	phillipvt@sse.co.za

ZR6AOC 475 0566 (H)


Member Craig ZR6CRW 795 1550 (H) craig.woods@absamail.co.za

West Rand members - we need your input!

To make this the best ham radio magazine in South Africa we need your input. Please submit articles, comments, suggestions etc.

Please send plain text with no formatting to the email address below.

In July 2003, we re-published an Anode Compendium on CD. It has the issues from July 2000 until June 2005. This included the new Adobe reader. It has been updated, check with the chairman for details.



zr6aoc@mweb.co.za

We need your input! Email us articles, comments and suggestions please. john_brock@telkomsa.net